



# CONSOLIDATION TEST DATA

## TIME CURVES

Constant Load Step: 11 of 18

Stress: 239.4 KPa



Project: ABC	Location: Boxboro, MA	Project No.: SETUP
Boring No.: B-1	Tested By: rh	Checked By: skw
Sample No.: S-1	Test Date: 00/00/0000	Depth: 5-7 feet
Test No.: CON1	Sample Type: Tube	Elevation: ---
Description: Moist, pale yellow brown black and reddish brown clayey silt		
Remarks: ASTM D2435		